



**TEST REPORT nr. S11116301**

**Safety (LVD)**

**Test item**

Description.....: BUSWAY  
 Trademark .....: POGLIANO BUSBAR  
 Model/Type.....: 1. 235100S1LPA  
 2. 234600S1LPA

**Test Specification**

Standard.....: EN 60529:1991 + A1:2000

**Client's name**.....: POGLIANO BUSBAR S.r.l.  
 Address.....: C.rso Allamano, 43 - 10095 GRUGLIASCO (TO) - ITALY

**Manufacturer's name** : Same as client  
 Address.....: --

**Report**

Tested by.....: M. Dal Santo - Technician

*M. Dal Santo*

Approved by.....: R. Beghetto - Laboratory Manager

*R. Beghetto*

Date of issue.....: 01.08.11

Contents .....: 18 pages




This test report shall not be reproduced except in full without the written approval of CMC.  
 The test results presented in this report relate only to the item tested.

CMC Centro Misure Compatibilità S.r.l.



**Setup**



**Result**

First Characteristic Numeral	Additional Letter	Result
IP6X	--	P
<b>Remarks:</b> No dust inside the enclosure. Test executed on model 235100S1LPA		

*Handwritten signature*

First Characteristic Numeral	Additional Letter	Result
IP6X	--	P
<b>Remarks:</b> No dust inside the enclosure. Test executed on model 234600S1LPA		


*Handwritten signature*

**Result:** The requirements are met

CMC Centro Misure Compatibilità S.r.l.



**Setup**



**Result**

Second Characteristic Numeral	Supplementary Letter	Result
IPX5	--	P
<b>Remarks:</b> No water inside the enclosure. Test executed on model 235100S1LPA		

*AdS*

Second Characteristic Numeral	Supplementary Letter	Result
IPX5	--	P
<b>Remarks:</b> No water inside the enclosure. Test executed on model 234600S1LPA		

*AdS*

**Result:** The requirements are met

CMC Centro Misure Compatibilità S.r.l.