



TEST REPORT nr. S11116302

Safety (LVD)

Test item

Description.....: BUSWAY
 Trademark: POGLIANO BUSBAR
 Model/Type.....: 1. 235100S1LPA
 2. 234600S1LPA

Test Specification

Standard.....: EN 60529:1991 + A1:2000

Client's name.....: POGLIANO BUSBAR S.r.l.
 Address.....: C.rso Allamano, 43 - 10095 GRUGLIASCO (TO) - ITALY

Manufacturer's name : Same as client
 Address.....: --

Report

Tested by.....: M. Dal Santo - Technician

M. Dal Santo

Approved by.....: R. Beghetto - Laboratory Manager

R. Beghetto

Date of issue.....: 01.08.11


Contents.....: 18 pages



This test report shall not be reproduced except in full without the written approval of CMC.
 The test results presented in this report relate only to the item tested.



Setup



Result

First Characteristic Numeral	Additional Letter	Result
IP5X	--	P
Remarks: No dust inside the enclosure. Test executed on model 235100S1LPA		


First Characteristic Numeral	Additional Letter	Result
IP5X	--	P
Remarks: No dust inside the enclosure. Test executed on model 234600S1LPA		

Result: The requirements are met

CMC Centro Misure Compatibilità S.r.l.



Setup



Result

Second Characteristic Numeral	Supplementary Letter	Result
IPX5	--	P

Remarks: No water inside the enclosure.
 Test executed on model 235100S1LPA

Handwritten signature

Second Characteristic Numeral	Supplementary Letter	Result
IPX5	--	P

Remarks: No water inside the enclosure.
 Test executed on model 234600S1LPA

Handwritten signature

Result: The requirements are met

CMC Centro Misure Compatibilità S.r.l.